

Uniform Mitigation Verification Inspection Pictures

Thursday, December 4, 2014

Sunrise Tower Association

888 Intracoastal Dr.


Ft. Lauderdale, FL 33304

ELEVATION





ROOF



136 Ceiling Grid	210 Rough
199 Bulking Final	210 Rough
SEPARATE PERMITS REQUIRED**	
150 Tin Cap	212 Wall Rough
152 Flat I.P.	212 Wall Rough
151 Mopon Sloped	213 Ceiling Rough
154 Tile I.P.	213 Ceiling Rough
153 Shingle I.P.	288 Pool Bond
199 Roof Final	282 Pool Niche B.
120 Shutter Fast.	Pool Deck B.
199 Shutter Panels	299 Final
180 Pool Steel	# ENGINEERING
102 Patio Steel	410 Rough
	469 Final

